



TENANT INFORMATION ADVISORY

Retention: February 28, 2022

November 1, 2021

21-029

BGE FEEDER AND SUBSTATION UPGRADES PHASE 1 SOUTH SUBSTATION T1 REPLACEMENT AND TRANSFORMER T1 REPLACEMENT

On November 15, 2021 between 12:01 a.m. and 5:00 a.m., maintenance is scheduled to perform Lock-Out/Tag-Out of the Tie Breaker in Building 192C, Tie Breaker in Building 192B, and the Transformer T2 breaker in Building 192C for the replacement of Transformer T1 in the South Substation. At this time, momentary outages may occur.

Once Lock-Out/Tag-Out is complete, removal and replacement of Transformer T1 will begin. Work will be ongoing until the new transformer is in place. Work is anticipated to be complete on or around February 16, 2022.

The outage should not affect any tenants. However, all tenants in the affected areas should take precautionary measures for a power outage during this time. In the event of a power outage, all life safety systems including fire protection and emergency lighting systems will operate as designed utilizing backup power.

If there should be an interruption to electrical services unexpectedly, please contact the Building Maintenance Supervisor's office at 410-859-7200.

Monday, November 15, 2021

12:01 a.m. through 5:00 a.m.

Equipment to be disconnected:

Transformer T1 at South Substation

(Momentary outages may occur)

Affected areas:

Switchgear #1: Lower and Upper Levels of Central Terminal, North Terminal Extension, North Terminal, and International Terminal; Lower and Upper Levels of Concourses C, D, DY, DX, and E; Third Floor (MAA); Fourth Floor (FAA); Runway 28 Deice Pad; and Airfield Lighting Vault

The point of contact is Niqui Clark, Resident Engineer (Hill International) at 602-326-8880 (cell).

**ELECTRONIC COPY
ORIGINAL ON FILE IN
AIRPORT OPERATIONS**

Gregory W. Solek
Director
Office of Airport Operations

DISTRIBUTION: B