



# TENANT INFORMATION ADVISORY

Retention: April 30, 2022

REVISED

March 21, 2022

22-007

## BGE FEEDER AND SUBSTATION UPGRADES PHASE 1 SOUTH SUBSTATION T1 REPLACEMENT – TRANSFORMER T1 REPLACEMENT

On **April 4**, 2022 at 12:01 a.m., maintenance is scheduled to perform Lock-Out/Tag-Out of the Tie Breaker in Building 192C, Tie Breaker in Building 192B, and the Transformer T2 breaker in Building 192C for the testing and acceptance of the newly installed Transformer T1 in the South Substation.

Once Lock-Out/Tag-Out is complete, testing of new controls installed for Transformer T1 will start. Work will be ongoing until the new transformer testing is complete and accepted. Work is anticipated to be complete on **April 5**, 2022.

If work is unable to occur on **April 4**, it will be rescheduled to occur on the backup date of **April 6** and be complete on **April 7**. This work should not affect any tenants. However, all tenants in the affected areas should take precautionary measures for a power outage during this time. In the event of a power outage, all life safety systems including fire protection and emergency lighting systems will operate as designed utilizing backup power.

Equipment to be connected: Transformer T1 at South Substation  
(No outages expected)

Affected areas: Switchgear #1 - Lower and Upper Levels of Central Terminal, North Terminal Extension, North Terminal, and International Terminal; Lower and Upper Levels of Concourses C, D, DY, DX, and E; Third Floor (MAA); Fourth Floor (FAA); Runway 28 Deice Pad; and Airfield Lighting Vault

If there should be an interruption to electrical services unexpectedly, please contact the Building Maintenance Supervisor's office at 410-859-7200.

Tenant Information Advisory 22-007

Page Two

The point of contact is Niqui Clark, Resident Engineer (Hill International) at 602-326-8880 (cell).

**ELECTRONIC COPY  
ORIGINAL ON FILE IN  
AIRPORT OPERATIONS**

---

Gregory W. Solek  
Director  
Office of Airport Operations

DISTRIBUTION: B